



Pipeline and Hazardous Materials Safety Administration

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2137-0584. Public reporting for this collection of information is estimated to be approximately 58.5 hours per response, including the time for reviewing instructions, gathering the data needed, and completing and reviewing the collection of information. All responses to this collection of information are mandatory. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden to: Information Collection Clearance Officer, Pipeline and Hazardous Materials Safety Administration (PHMSA), PHP-30, 1200 New Jersey Ave SE, Washington, D.C. 20590

Pipeline Safety

2021 Gas Base Grant Progress Report

for

IDAHO PUBLIC UTILITIES COMMISSION

Please follow the directions listed below:

- 1. Review the entire document for completeness.
- 2. Review and have an authorized signatory sign and date page 2.
- 3. Scan the signed document to your computer and email it to Carrie.Winslow@dot.gov.



Electronic Submission Date: 3/2/2022 3:47:00 PM



Pipeline and Hazardous Materials Safety Administration 1200 New Jersey Avenue, SE Washington DC 20590

OFFICE OF PIPELINE SAFETY

2021 Gas Base Grant Progress Report

Office: IDAHO PUBLIC UTILITIES COMMISSION

Authorized Signature

Printed Name

Title



Date

PROGRESS REPORT ATTACHMENTS (GAS)

PHMSA Form No. PHMSA F 999-92

Attachment 1: State Jurisdiction and Agent Status over Facilities.

Attachment 2: State Field Inspection Activity

Attachment 3: Facilities Subject to State Safety Jurisdiction

Attachment 4: Pipeline Incidents

Attachment 5:State Compliance Actions

Attachment 6: State Record Maintenance and Reporting

Attachment 7: State Employees Directly Involved in the Pipeline Safety Program

Attachment 8: State Compliance with Federal Regulations

{there is no attachment 9}

Attachment 10: Performance and Damage Prevention Questions



Attachment 1 - Stats on Operators

STATE JURISDICTION AND AGENT STATUS OVER GAS FACILITIES AS OF DECEMBER 31, 2021

Operator Type		State Agency Jurisdiction/ Agent Status			erators pected	No. of Inspection Units	Units Inspected	
	No ¹	Yes		#	%		#	%
Distribution								
Private		X/60105	3	3	100.0%	10	10	100.0%
Municipal	A		0	0	N/A	0	0	N/A
Master Meter		X/60105	0	0	N/A	0	0	N/A
LPG		X/60105	0	0	N/A	0	0	N/A
Other	A		0	0	N/A	0	0	N/A
Transmission								
Intrastate		X/60105	3	3	100.0%	3	3	100.0%
Interstate	F		0	0	N/A	0	0	N/A
LNG								
Intrastate		X/60105	1	1	100.0%	1	1	100.0%
Interstate	A		0	0	N/A	0	0	N/A
Other								
Gathering Lines		X/60105	1	1	100.0%	1	1	100.0%
Offshore Facilities	A		0	0	N/A	0	0	N/A
Total	<u> </u>		8	8	100.0%	15	15	100.0%

¹Codes: A - None in state and does not have jurisdiction;

- B State does not have jurisdictional authority (Provide current status or action being taken to obtain authority in notes section below)
- F No, State is currently not an interstate agent.

X/60105P = Yes, I have Section 60105 (Certification) over some of the operator type (meaning: I have 60105 authority over some, but not all of this operator type and do not have a 60106 agreement with PHMSA to inspect them). These operators are identified in the notes below.

X/IA - Yes, I have Interstate Agent jurisdiction over this type of operator

Distribution "Other" - ie Co-ops, Public Utility Districts, etc.

States should explain any special circumstances

General Instructions - All above facilities should only include facilities as defined by federal pipeline regulations and should not include extended jurisdiction by state regulation.

Attachment 1 Notes:

Idaho has 5 operators: 1. Avista (distribution only), 2. Dominion (transmission and distribution), 3. Intermountain Gas



Company (transmission, distribution and LNG), and 4. Northwest Gas Processing (gathering only). 5.New for 2021 Douglas Pipeline added as an operator (transmission only).



Attachment 2 - State Inspection Activity

TOTAL STATE FIELD INSPECTION ACTIVITY AS OF DECEMBER 31, 2021

Operator Type	Standard Comprehensive	Design, Testing and Construction	On-Site Operator Training	Integrity Management	Operator Qualification	Investigating Incidents or Accidents	Damage Prevention Activities	Compliance Follow-up	Total
Distribution									
Private	131.500	111.000	0.000	9.500	23.000	1.000	2.500	0.000	278.500
Municipal	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
Master Meter	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
LPG	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
Other	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
Transmission									
Intrastate	9.500	0.000	0.000	15.000	2.000	0.000	0.000	0.000	26.500
Interstate	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
LNG									
Intrastate	5.500	0.000	0.000	0.000	0.000	2.000	0.000	0.000	7.500
Interstate	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
Other									
Gathering Lines	12.500	0.000	0.000	0.000	0.500	0.000	0.000	0.000	13.000
Offshore Facilities	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000	0.000
Total	159.000	111.000	0.000	24.500	25.500	3.000	2.500	0.000	325.500

Drug and Alcohol

Total Count of Drug and Alcohol Inspections

Attachment 2 Notes

Per PHMSA guidance the 'training' in our Idaho inspection days tracking was corrected and moved to OQ.

Total count of drug and alcohol were entered for full program I.A. inspections as per PHMSA guidance.

Attachment 3 - List of Operators

GAS FACILITIES SUBJECT TO STATE SAFETY JURISDICTION AS OF DECEMBER 31, 2021

Operator	(Оре	Distrerator type &	ibution & Inspec	tion Ur	nits)	(Operato	nission or type & on Units)	` -	LNG(Operator type & Inspection Units)		Other (Operator type & Inspection Units)	
Business Name Operator ID Address	Private	Municipal	Master Meter	LPG	Other	Intrastate	Interstate	Intrastate	Interstate	Gathering Lines (Juris- dictional)	Offshore Facilities (State Waters)	
Avista Corporation 31232 1411 E. Mission, Spokane, WA 99220	5	0	0	0	0	0	0	0	0	0	0	
Dominion Energy 12876 1040 W. 200 S., Salt Lake City, UT 84145	1	0	0	0	0	1	0	0	0	0	0	
Douglas Pipeline Co 31442 3829 Willow Ave Suite 203, Pittsburg, PA 15234	0	0	0	0	0	1	0	0	0	0	0	
Intermountain Gas Company 8160 555 South Cole, Boise, ID 83707	5	0	0	0	0	1	0	1	0	0	0	
Northwest Gas Processing, LLC 39370 15021 Katy Freeway, Suite 400 Houston, TX 77094	0	0	0	0	0	0	0	0	0	1	0	

	Distribu (Operator type & In					Transmission (Operator type & Inspection Units)		LNG(Operator type & Inspection Units)		Other (Operator type & Inspection Units)	
											Offshore
										Gathering	Facilities
	Private	Municipal	Master	LPG	Other	Intrastate	Interstate	Intrastate	Interstate	Lines (Juris-	(State
	1 11vate	Municipai	Meter	LIG	Other	Inci astate	interstate	inci astate	Interstate	dictional)	Waters)
Inspection Unit totals by type	11	0	0	0	0	3	0	1	0	1	0

Total Operators 5

Attachment 3 Notes:

Avista now has (5) different inspection units which has changed from 4. (2) of them have been and still are often grouped for logistical reasons and proximity.



Attachment 4 - Incidents/Accidents

SIGNIFICANT⁴ GAS INCIDENTS/ACCIDENTS JANUARY 1, THROUGH DECEMBER 31, 2021

Date of Incident	Location - City/County/etc.	System Type	Injuries #	Fataliti	esProperty Damage ³ \$	Operator Cause Code ¹	State Cause Code ¹
02/17/2021	NO LOCATION	LNG	0	0	\$3,978,532.00	A1	A1
Name of Operator:	INTERMOUNTAIN GA	S CO					
Operator ID:	8160		Report N	o:	20210003		

Summary²

On Thursday, February 4, 2021 a Plant Operator was working on the roof of the LNG tank and audibly and visually

discovered a non-hazardous leak. The non-hazardous leak is under a steel backing plate that is welded to the roof of the

LNG tank. The backing plate is part of the support system for the walking platform. Because the backing plate is not fully

welded, water accumulated between the backing plate and the LNG tank roof, ultimately leading to a non-hazardous

corrosion leak. An estimated 300 CFH is venting to the atmosphere.

Intermountain Gas Company (IGC) hired an engineering consultant on February 11, 2021 to evaluate repair options. On

February 17, 2021 at 11:10 a.m. MST, using data provided by the engineering consultant, IGC determined the LNG tank

will be taken out of service to make repairs, which is expected to exceed \$50,000, at which time IGC notified the NRC. As of February 17, 2021, the LNG tank had 3,093,114 gallons of LNG. To allow for the offload and vaporization of the

LNG, the LNG tank will be taken out of service in June 2021.

The estimated volume of commodity released unintentionally (Part A, Question 9) is 201.6 MCF as of March 4, 2021.

This quantity will be revised for the Final report.

Estimated cost of Operator's property damage & repairs (Part C, Question 1.b.) is \$500,000. This cost will be revised for

the Final report.

03/01/2021 GOSHEN GD 0 0 \$26,495.00 F1 F1

Name of Operator: INTERMOUNTAIN GAS CO

Operator ID: 8160 Report No: 20210031

Summary²

Intermountain Gas Company (IGC) was notified of an outside gas odor in Goshen, ID (an

unincorporated community in Bingham

County) at 18:07 on February 27, 2021. After arriving on site at 18:51, a Company first responder

found a 3" relief valve at a

district regulator in the full open position at which time additional personnel was dispatched to the



scene. The regulators at the

location of the relief valve were inspected and found to be operating correctly. Company personnel then began inspecting the

regulators at a regulator station located 3.7 miles west of the blowing relief valve that supplies gas to the same 200 psig MAOP

pipeline. The primary regulator at the second regulator station was shut in at 21:45 at which time the system pressure dropped to

170 psig; however, the relief valve was still in the open position. The relief valve was isolated at 12:28 on February 28, 2021. It

was determined hydrocarbons had accumulated and froze causing the relief valve to stick in the open position.

The morning of March 1, 2021 Company personnel inspected and repaired the primary regulator at the second regulator station. A

yellow/white powder was found on the seat, diaphragm and pilot components which was the cause of the regulator failure that

resulted in the relief valve opening. The powder was cleaned off all surfaces and the soft components were replaced.

At 11:52 on March 1, 2021 the engineering department calculated the gas loss for this release at which time it was discovered the

0

3 million cubic feet reporting threshold was exceeded.

10/28/2021

RATHDRUM

GD

0

\$778,199.00

C3

C1

Name of Operator:

AVISTA CORP

Operator ID:

31232

Report No:

20210098

Summary²

At approximately 10:00 a.m. PDT on October 28, 2021, PG Contractors, a third-party contractor, was installing

telecommunications infrastructure using a horizontal directional drill when they severed a 2" polyethylene (PE) main at the

intersection of Christine Street and Beechwood Street in front of 6997 W Christine St., Rathdrum, Idaho. The PE pipe operated at

a pressure of approximately 55 psig with an MAOP of 60 psig, was at a depth of 36 inches, and locate marks were present and

accurate. Avista was notified at 10:13 a.m. PDT and was on site at 10:20 a.m. PDT. The Northern Lakes Fire District responded

and evacuated 3 nearby residences at 6971, 6997 and 7025 W Christine Street. The location of the damage required squeezing

the 2" main in three locations as it was close to a tee. The squeezes were complete at 11:43 a.m. PDT to control the flow of gas.

The fire department left once the scene was secure. Underground barhole readings were taken in front of the three evacuated

houses and showed 0 percent LEL. Inside gas readings were taken at 6997 W Christine Street at approximately 12:10 p.m. PDT

and showed readings between 10% and 70% LEL. The Gas Serviceman exited the house and left the doors open to air out the

house.

At approximately 12:30 p.m. PDT the homeowners at 7025 W Christine Street came home and requested to enter their house. A

Gas Serviceman checked each room of the house with a combustible gas indicator and found readings of 0% LEL, so the Gas

Serviceman cleared the house for the homeowners to reenter.

Shortly thereafter, the homeowners at 6997 W Christine Street requested to get back into their house.



The Gas Serviceman

checked each room with a combustible gas indicator, which now read 0% LEL and he allowed the homeowners back in their

house. At this time, the gas and electricity were still shut off to the house and the electric meter had to be re-installed. After

turning the electricity back on the homeowner reported popping noises coming from the furnace. The Gas Serviceman checked

near the furnace and found 0% LEL and decided to turn the furnace off at the thermostat. While entering the house from the

Form PHMSA F 7100.1 (rev 4-2019) Page 12 of

12

Reproduction of this form is permitted

garage, the Gas Serviceman saw a red glow above his head which was an ignition of gas at approximately 12:46 p.m. PDT. The

Gas Serviceman exited through the open garage door and the male homeowner exited through the rear garage access door.

Individuals on scene then helped to get the female homeowner out of the upstairs of the house through a window. Shortly

thereafter the building was consumed by flames. Operator personnel on scene called 911 immediately after the gas ignited and

the Northern Lakes Fire District was on scene at approximately 12:57 p.m. PDT. The female homeowner was assessed by EMTs

on site and the male homeowner went to the hospital to be treated for second degree burns on his forearm but was not admitted.

Preliminary investigation suggests that there was a pocket of gas inside the house in a location that could not be detected by the

Gas Serviceman's instrument. It was that pocket of gas that ignited causing the fire. The building was deemed a total loss with a

value exceeding \$122,000 resulting in this incident being reportable. Avista denies liability for damages and injuries associated

with this incident.

¹High Level Cause Codes: A - Corrosion failure; B - Natural Force Damage; C - Excavation Damage; D - Other Outside Force Damage; E - Pipe, Weld or Joint Failure; F - Equipment Failure; G - Incorrect Operation; H - Other Incident Cause; IP - Investigation Pending;

²Please include a summary or report of the state agency's investigation of each of the above incidents.

³Interstate agents should use the 191.3 Incident definition for listing incidents investigated on interstate facilities.

Attachment 4 Notes

The LNG incident is considered to be located in Nampa, ID.



Attachment 5 - Stats on Compliance Actions

STATE COMPLIANCE ACTIONS -- CALENDAR YEAR (CY) 2021

Probable Violation Categories	Intra	istate	Interstate
Number carried over from all previous CY's	0		0
Number Found During CY	12		0
Number submitted for DOT action [60106 Agreement agonly]	ent 0		0
Number corrected during CY (including carry over from previous year(s))	12		0
Number to be corrected at end of CY (including carry over	er) 0		0
Number of Compliance Actions Taken ¹			
•	2		
Civil Penalties			
Number assessed during CY 0)		
Dollars assessed during CY \$	00.00		
Number collected during CY 0)		
Dollars collected during CY \$	00.00		

¹Do not double count for a related series of actions.

Attachment 5 Notes

(12) separate compliance notices and letters during the CY.

IPUC also recieved a whistleblower complaint regarding OQ compliance. IPUC conducted an investigation these claims. The case is continuing into the next year. Civil penalties are expected pending commission approval. IPUC also recieved a whistleblower complaint regarding OQ compliance. IPUC conducted an investigation of



Attachment 6 - List of Records Kept

GAS STATE RECORD MAINTENANCE AND REPORTING DURING CY 2021

Records Maintained by the State Agency

Pipeline Safety Program Annual Certification/Progress Report

Operator Annual Reports

Common Ground Alliance

Compliance Actions

Damage Prevention Program

Inspection Field Days

Annual Inspection Schedule

Operator Incident/Accident

PHMSA Correspondence

PUC Pipeline Safety Program Plan (POP)

PHMSA Program Evaluation

OPS Grants- Base Grant Application

Safety Related Condition Reports

Pipeline Training

T & Q Seminars

NAPSR Surveys

Inspection Reports: 2017, 2018, 2019, 2020, 2021

Reports Required from Operators

Incident Reports as per IPUC rule Operators Annual Reports

Attachment 6 Notes

NAPSR Surveys are conducted online. A receipt is not always given from the Survey Monkey website for Idaho retention.



Attachment 7 - Staffing and TQ Training

STATE EMPLOYEES DIRECTLY INVOLVED IN THE GAS PIPELINE **SAFETY PROGRAM DURING CY 2021**

Name/Title		# Months	Qual. Cat.
Supervisor		•	
Jeff Brooks			
Program Manager	50.000	0.5	NA
Ulmer, Darrin			
Program Manager	40.000	8	NA
Inspector/Investigator	·		
Jeff Brooks			
Inspector	98.000	12	III
Perkins, Bruce			•
Inspector	100.000	12	II
Ulmer, Darrin			•
Inspector	60.000	8	II

Employee Type	No. of Staff	Person-Years
Supervisor	2	0.290
Damage Prevention/Technical	0	0.000
Inspectors/Investigators	3	2.380
Clerical/Administrative	0	0.000
Total	5	2.670



Attachment 7 Notes

Kyle Russo was not with the program in 2021 - he left prior to 2021. Darrin Ulmer left the program in September. Jeff Brooks was the new program manager as of the middle of December 2021.



Attachment 8 - Compliance with Federal Regulations

STATE COMPLIANCE WITH FEDERAL REQUIREMENTS AS OF DECEMBER 31, 2021

No.	Effective Date	Impact	Adoption Date	AdoptionStatus
1		Penalties Substantially same as DOT (\$225,134/\$2,251,334). State minimum penalties of at least (\$100,000/\$1,000,000). Indicate actual otes.	04/1970	Adopted Other
Note ¹	\$2,000 per ea	ach violation per day the violation persists. \$200,000 maximum for any r	elated serie	s of violations.
2	Part 192 An	nendments	•	
1-115	Pre 2011	[All applicable amendments prior to and including 2010]	12/31/2010	OAdopted
Note ¹				
116 - 76 FR 5494	4/4/2011	Mechanical Fitting Failure Reporting Requirements	04/2012	Adopted
Note ¹				
117-76 FR 35130	8/15/2011	Control Room Management/Human Factors	04/2013	Adopted
Note ¹				
118 - 78 FR 58897	10/25/2013	Administrative Procedures, Updates, and Technical Corrections (Not applicable to States)	04/2016	Adopted
Note ¹				
119 - 80 FR 168	3/6/2015	Periodic Updates of Regulatory References to Technical Standards and Miscellaneous Edits	04/2016	Adopted
Note ¹				
120 - 80 FR 12779	10/1/2015	Miscellaneous Changes to Pipeline Safety Regulations (Part 192.305 DELAYED)	04/2016	Adopted
Note ¹				



		- y		
Note ¹				
123 - 82 FR 7972	3/24/2017	Operator Qualification, Cost Recovery, Accident and Incident Notification, and Other Pipeline Safety Changes	07/2018	Adopted
Note ¹				
124 - 83 FR 58694	1/22/2019	Use of Plastic Piping Systems in the Transportation of Natural and Other Gas	07/2021	Adopted
Note ¹	-	ough CFR and Commission Safety Regulations Order 35095 (Rule 201 annual editions.	1). Code of F	ederal Regulations have been updated to the
125 - 84 FR 52180	7/1/2020	Pipeline Safety: Safety of Gas Transmission Pipelines: MAOP Reconfirmation, Expansion of Assessment Requirements, and Other Related Amendments	07/2021	Adopted
Note ¹		ough CFR and Commission Safety Regulations Order 35095 (Rule 201 annual editions.	1). Code of F	ederal Regulations have been updated to the
126 - 86 FR 2210	3/12/2021	Pipeline Safety: Gas Pipeline Regulatory Reform (Delayed to 3/21) (Delayed Compliance date 10/12/2021)	07/2021	Adopted
Note ¹		ough CFR and Commission Safety Regulations Order 35095 (Rule 201 annual editions.	1). Code of F	ederal Regulations have been updated to the
3	Part 193 Ar	nendments (applicable only where state has jurisdiction over LNG	5)	
1-23	Pre 2011	[All applicable amendments prior to and including 2010]	12/2010	Adopted
Note ¹				
24 - 78 FR 58897	10/25/2013	Administrative Procedures, Updates, and Technical Corrections	04/2016	Adopted
Note ¹				
25 - 80 FR 168	3/6/2015	Periodic Updates of Regulatory References to Technical Standards at Miscellaneous Edits	nd 04/2016	Adopted
Note ¹				
4	Part 199 - D	Drug Testing	03/2001	Adopted
Note ¹				
5	Part 199 Ar	nendments		

07/2018


Adopted

Expanding the Use of Excess Flow Valves in Gas Distribution

Systems to Applications Other Than Single-Family Residences

121 - 81 FR 70989 4/14/2017

1-24	Pre 2011	[All applicable amendments prior to and including 2010]	12/2010	Adopted
Note ¹				
25 - 78 FR 58897	10/25/2013	Administrative Procedures, Updates, and Technical Corrections	04/2016	Adopted
Note ¹				
26 - 80 FR 168	3/6/2015	Periodic Updates of Regulatory References to Technical Standards and Miscellaneous Edits	04/2016	Adopted
Note ¹				
27 - 82 FR 7972	3/24/2017	Operator Qualification, Cost Recovery, Accident and Incident Notification, and Other Pipeline Safety Changes	07/2018	Adopted
Note ¹				
28 - 84 FR 16770	4/23/2019	Conforming Amendments and Technical Corrections to Department Rules Implementing the Transportation Industry Drug Testing Program	07/2021	Adopted
Note ¹		Safety Regulations Order 35095 is expected to be amended within the yearal Regulations to the most current eCFR editions.	ear 2022 to	o incorporate by reference the pipeline safety
6	State Adop	tion of Part 198 State One-Call Damage Prevention Program		
a.		Mandatory coverage of areas having pipeline facilities	04/1990	Adopted
Note ¹				
1	-			



g. Note ¹	Mandatory notification of excavators/public	07/2002	Adopted
h.	Civil penalties/injunctive relief substantially same as DOT	07/2018	Adopted but Different Dollar Amounts
Note ¹	Current law provides for \$1,000 penalty for second occurance; \$5,000 for any s	subsequent occur	rrences.

¹If Adoption Status is No, Please provide an explanation

State Attendance at 2021 NAPSR Regional Meeting: Frequency of General Legislative Session: Annually

Attended full time (Lead rep or alternative pipeline staff)

Attachment 8 Notes

Commission Safety Regulations Order 35095 (July, 2021) is expected to be amended within the year 2022 to incorporate by reference the Title 49 pipeline safety Code of Federal Regulations to the most current eCFR editions.

Commission Safety Regulations Order 35095 is expected to be amended within the year 2022 to incorporate by reference the pipeline safety Code of Federal Regulations to the most current eCFR editions.

All enforcement authority for damage prevention is held within Idaho Division of Building Safety's Damage Prevention Board. The Commission does hold a seat on the 11 person board but does not have any directive authority over it.



Attachment 10 - Performance and Damage Prevention Questions

CALENDAR YEAR (CY) 2021

Planned Performance: What are your Planned Annual and Long-term goals for your Pipeline Safety Program?

The IPUC Pipeline Safety Program is committed to improving our safety program. The Commission's annual goals are to ensure Idaho jurisdictional pipeline operators are providing the safe transportation and delivery of natural gas to its customers and doing this without affecting the safety of the public. This is accomplished by a comprehensive program of inspections and audits of the companies' records and field equipment and following-up on each incident and non-compliance found. The Commission has added a new operator into their inspection plan. The Commission's inspection staff will continue conducting construction inspections, followup inspections of the high-pressure service sets (HPSS/farm taps) and will continue to attend the construction of the renewable natural gas pipelines. The Commission's goal is to get a new inspector hired to begin the TQ learning path and be able to lead basic inspections with the long term goal of maintaining a full inspection staff.

Past Performance: What did the Pipeline Safety Program accomplish during the subject year (to this document) to contribute toward the program's annual and long-term goals?

Five Intrastate operators within the Commission's jurisdiction were inspected for the safe transportation and delivery of natural gas within the state according to the Commission's approved program of operating procedures. Any deficiencies found were documented and discussed with the operators for corrective action(s). Follow-up inspections were performed as required. IPUC inspectors completed 13 T&Q courses in 2021. The PUC's program manager vacated the position but was replaced with one of the existing PUC inspectors. The PUC is attempting to hire a third inspector to fill the vacancy.

- 1. Has the state or agency reviewed the Damage Prevention Assistance Program (DPAP) document in the last twelve months? No
- 2. Has the state or agency developed or is in the process of developing a plan to address the nine elements contained in the PIPES Act of 2006 for an effective State Damage Prevention Program?

Yes

If yes to question 2, where does the state or agency stand on implementation of the nine elements contained in the PIPES Act of 2006? Please provide a description of how the state or agency has or will meet each element. If not, please provide a brief passage explaining the reasons why the state or agency has not.

2006? Please provide explaining the reason:

The Commission h develop a State Da prevention is held v board but would no State Damage Prevention law, eling accordance with the review operator's da Noted deficiency(s) deficiencies result in established in the Commission.

Attachment 10 Notes The Commission has continued to participate in the statewide coalition for damage prevention but does not have statutory authority to develop a State Damage Prevention Program that would have any enforcement ability. All enforcement authority for damage prevention is held within Idaho Division of Building Safety's Damage Prevention Board. The Commission does hold a seat on the board but would not have any directive authority over it. The board's objective plan has addressed the nine elements for an effective State Damage Prevention Program. The Commission supports the program through an alliance with (two) one-call centers, Operator's public awareness programs, and utility coordinating councils. The goal of the coalition is to improve the underground damage prevention law, eliminate as many exemptions as possible, educate the public and establish an effective enforcement mechanism in accordance with the 9 elements contained in the PIPES Act. During annual audit(s) of each operator, the Commission continues to review operator's damage prevention program against rules and standards to ensure the programs processes are in place and effective. Noted deficiency(s) are documented on the IPUC Form 1 and the appropriate section of the PHMSA checklist. Significant process deficiencies result in immediate corrective actions and if needed a compliance action. Procedures for probable violation process established in the Commission's program operating procedures will be followed.

