## **Idaho PUC Pipeline Safety Inspection Summary**

Inspector(s):	Perkins			20-Aug-20
Company/Owner: Intermountain Gas Company Unit/OPID: 81				
Company/Owner: Intermou		intain Gas Company	Johnty OPID:	8160
Inspection Type & Time (1 day)		To	tal Inspection Days:	1
Standard: Construction:	1 Training:	(T)(D) Integrity Managem	ent: Incident:	
M/M: Follow-up: OQ: Damage Prevention: D&A:				
Inspection Summary				
A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company.				
20 Aug 2020: (1.0 Construction) Observed a Das-co crew installing a new ¾" service line at 1527 N Pineview Lane, Boise, Idaho. Contractor installed the new line and a stub with Continental cap and go. When pressure testing the line, a leak was discovered on the cap and go at the inlet and outlet. Fitting was cut out and submitted to IGC for testing or sending back to manufacturer for testing. (Possible Failed Fiting Report) All procedures were followed. Typed Observed a Das-co crew installing a new ¾" service line at 235 W Addeson St, Meridian, Idaho. All procedures were followed. Typed up report				
Areas observed during this project were: Excavating, line locating, plastic joining, backfilling/bedding, pressure testing and EFV test.				
Attachments: IPUC Form 4 Construction Inspections Das-co daily Itineraries located in file for the project. OQ's for all observed employees are located in file for the project. Pictures of Job tickets and failed fitting.				
Corrective Action Required:		w-up Required:	Yes X No	
Yes No	X	Failed Fitting Report?	by (date):	20-Feb-21
Inspector (Lead):	1 1 29/11		Date:	
Bruce Perkins		yer	8/20/2020	
Reviewer:  Darrin Ulmer	Harristan		Date:	20 00