

Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	Ulmer/Perkins/Russo	Date(s):	Aug 27-31, 2018
Company/Owner:	Avista Utilities	Unit/OPID:	Moscow
Inspection Type & Time (1 day, 0.5 day)	Total Inspection Days:		13
Standard: <input type="text" value="8.5"/>	Construction: <input type="text" value="1.5"/>	Training: <input type="text"/>	(T)(D) Integrity Management: <input type="text"/>
Incident: <input type="text"/>	M/M: <input type="text" value="3"/>	Follow-up: <input type="text"/>	OQ: <input type="text"/>
	Damage Prevention: <input type="text"/>	D&A: <input type="text"/>	
Inspection Summary			
<p>A construction inspection was performed on Avista in the Moscow/Lewiston area.</p> <p>August 27, 2018: (3 Standard) Traveled to Lewiston, ID to conduct construction inspection.</p> <p>August 28, 2018: (1.5 Construction, 1.5 MM) An Avista crew was installing a new service line to a foundation for a new residence. Installing a new 3/4" plastic service line to a new residence foundation on Hampton Ct in Moscow.</p> <p>Areas observed during this project were: pinching off, plastic pipe joining, hot tapping, pressure testing, purging, service line installation (tracer wire), riser placement and backfilling.</p> <p>Inspectors went onto University of Idaho campus to investigate about the possibility of there being a master meter. Made contact with campus personnel and briefed them on their responsibilities.</p> <p>August 29, 2018: (1.5 Standard, 1.5 MM) Met with Steve Aubuchon (Clarkston Operations Manager) and some engineers from Spokane to witness a pilot program utilizing an underwater submersible to monitor pipeline patrols crossing the Snake and Clearwater Rivers.</p> <p>Inspectors went onto Lewis and Clark College campus to investigate about the possibility of there being a master meter. Made contact with campus personnel and briefed them on their responsibilities.</p> <p>August 30, 2018: (3 Standard) Traveled back to Boise, ID.</p> <p>August 31, 2018: (1 Standard post) Typed the construction inspection report. Completed IPUC forms.</p> <p>Attached: IPUC Form 1, Inspection Summary IPUC Form 4, Construction Inspections</p>			

Idaho PUC Pipeline Safety Inspection Summary

Corrective Action Required:		Follow-up Required:		Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>		by (date):		
Inspector (Lead):		Date:		31 Aug 2018	
Reviewer:		Date:		Aug 31, 2018	