

Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	Ulmer/Russo/Perkins	Date(s):	20-Aug-19
Company/Owner:	Intermountain Gas Company	Unit/OPID:	8160
Inspection Type & Time (1 day)	Total Inspection Days:		3
Standard: <input type="checkbox"/>	Construction: <input checked="" type="checkbox"/> 3	Training: <input type="checkbox"/>	(T)(D) Integrity Management: <input type="checkbox"/> Incident: <input type="checkbox"/>
M/M: <input type="checkbox"/>	Follow-up: <input type="checkbox"/>	OQ: <input type="checkbox"/>	Damage Prevention: <input type="checkbox"/> D&A: <input type="checkbox"/>
Inspection Summary			
<p>A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company.</p> <p>20 Aug 2019: (3.0 Construction) Observed the crew performing a new service bore of a 3/4" PE to 935 W. Hubbard in Kuna to replace an existing HPSS. The crew was excavating the existing service at the house upon arrival in preparation for the bore. They bored in and pulled back the 3/4" PE to the HPSS bellhole. Did not witness the completion of the project.</p> <p>Areas observed during this project were: Excavating, Boring</p> <p>20 Aug 2019: (.0 post Construction) Type construction report.</p> <p>Attachments: IPUC Form 4 Construction Inspections Das-co Daily Itineraries located in file for the project. OQ's for all observed employees are located in file for the project.</p>			
Corrective Action Required:		Follow-up Required:	
Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
		by (date):	
Inspector (Lead):		Date:	
Darrin Ulmer		20 Aug 2019	
Reviewer:		Date:	