


Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	Perkins, Russo	Date(s):	16-17 May 2019
Company/Owner:	Intermountain Gas Company	Unit/OPID:	8160
Inspection Type & Time (1 day, 0.5 day)	Total Inspection Days:		2
Standard: <input type="checkbox"/>	Construction: <input checked="" type="checkbox"/> 2	Training: <input type="checkbox"/>	(T)(D) Integrity Management: <input type="checkbox"/> Incident: <input type="checkbox"/>
M/M: <input type="checkbox"/>	Follow-up: <input type="checkbox"/>	OQ: <input type="checkbox"/>	Damage Prevention: <input type="checkbox"/> D&A: <input type="checkbox"/>
Inspection Summary			
<p>A construction inspection was performed on DAS-CO, a contractor for Intermountain Gas Company.</p> <p>16-17 May 2019: (2 Construction)</p> <p>Observed the Dasco crew installing and tapping a new 3/4" service in the Neville Ranch subdivision at 3610 W. Miners Farm, Boise. Typed up report</p> <p>Areas observed during this inspection were: Locating, Excavating, Tie-ins, Tapping, Backfilling.</p>			
Attachments:			
<p>IPUC Form 4 Construction Inspections</p> <p>DAS-CO Daily Itineraries located in file for the project.</p> <p>OQ's for all observed employees are located in file for the project.</p> <p>Photo's are located in file for the project.</p> <p>PHMSA Form 15, OQ Field Inspection Form</p>			
Corrective Action Required:		Follow-up Required:	
Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
		by (date):	
Inspector (Lead):		Date:	
Bruce Perkins		20 May 19	
Reviewer:		Date:	
		20 May 2019	