



Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	Perkins	Date(s):	16-19 Apr 2019
Company/Owner:	Intermountain Gas Company	Unit/OPID:	8160
Inspection Type & Time (1 day, 0.5 day)	Total Inspection Days:		4
Standard: <input type="checkbox"/>	Construction: <input type="checkbox"/> 3.5	Training: <input type="checkbox"/>	(T)(D) Integrity Management: <input type="checkbox"/> Incident: <input type="checkbox"/>
M/M: <input type="checkbox"/>	Follow-up: <input type="checkbox"/>	OQ: <input type="checkbox"/> 0.5	Damage Prevention: <input type="checkbox"/> D&A: <input type="checkbox"/>
Inspection Summary			
<p>A construction inspection was performed on DAS-CO, a contractor for Intermountain Gas Company.</p> <p>16-18 April 2019: (2.5 Construction .5 OQ)</p> <p>Crew was installing a 8" steel main as part of a road widening project and tying into an existing 10" main which when completed will operate at 390 PSI. (Project # 19IGC-2001).</p> <p>Areas observed during this project were: Other utility location, Welding, Welding inspection by QCI, Excavation, Pot holing, Abandoning, Main line installation (tracer wire), Tie-ins and Backfilling.</p> <p>An operator qualification inspection was performed on Gordon Finlay of QCI (Subcontracted by IGC) that was performing as the Certified Welding Inspector.</p> <p>19 April 2019: (1 post Construction)</p> <p>Type construction report.</p> <p>Attachments:</p> <p>IPUC Form 4 Construction Inspections DAS-CO Daily Itineraries located in file for the project. OQ's for all observed employees are located in file for the project. Photo's are located in file for the project. PHMSA Form 15, OQ Field Inspection Form</p>			
Corrective Action Required:		Follow-up Required:	
Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
Inspector (Lead):		by (date):	
Bruce Perkins 		Date: 19 APR 19	
Reviewer:		Date:	
		Date: 22 APR 19	