## **Idaho PUC Pipeline Safety Inspection Summary**

Inspector(s):	Perkins/Russo		Date(s):	2-Jul-19
			l., , ,,,,,,	
Company/Owner:	mpany/Owner: Intermountain Gas Company		Unit/OPID:	8160
Inspection Type & Time (1 day, 0.5 day)  Total Inspection Days: 2.5				
Inspection Type & Time (1 day, 0.5 day)  Total Inspection Days: 2.5				
Standard: Construction: 2.5 Training: (T)(D) Integrity Management: Incident:				
M/M: Follow-up: OQ: Damage Prevention: D&A:				
Inspection Summary				
A construction inspection was performed on DAS-CO, a contractor for Intermountain Gas Company.				
<u>2 July 2019:</u> (2.0 Construction)				
Crew was installing new 3/4" service lines to 3 new homes, using saddle T's off of 2" main and installing and pressure testing associated piping and EFV's				
Areas observed during this project were: Line locations, trenching, installing new service line and tracer wire, installing saddle T's and EFV, pressure testing, bedding/backfilling,				
<u>5 July 2019:</u> (.5 post Construction) Type construction report.				
Attachments: IPUC Form 4 Construction Inspections DAS-CO Daily Itineraries located in file for the project. OQ's for all observed employees are located in file for the project.				
Corrective Action Required: Follow-up Required: Yes No X  Yes No X  Inspector (Lead): Date:				
Bruce Perkins of Grant G				
Reviewer:	Jan Alla	111	Date:	1. 2019