



Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	Russo	Date(s):	8-Oct-19
Company/Owner:	Intermountain Gas Company	Unit/OPID:	8160
Inspection Type & Time (1 day)	Total Inspection Days: 1		
Standard: <input type="checkbox"/>	Construction: <input checked="" type="checkbox"/> 1	Training: <input type="checkbox"/>	(T)(D) Integrity Management: <input type="checkbox"/> Incident: <input type="checkbox"/>
M/M: <input type="checkbox"/>	Follow-up: <input type="checkbox"/>	OQ: <input type="checkbox"/>	Damage Prevention: <input type="checkbox"/> D&A: <input type="checkbox"/>
Inspection Summary			
<p>A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company.</p> <p>8 Oct 2019: (1.0 Construction) Observed a Dasco crew installing a branch service for two homes in Boise. Observed them excavating for the services. They exposed the stub and laid the service in the trench to install. Pressure tested and tied in. I had left before the gas was purged and backfilled. Typed up report</p> <p>Areas observed during this project were: Excavating, Line locating, Coupling, Pressure testing</p> <p>Attachments: IPUC Form 4 Construction Inspections Das-co Daily Itineraries located in file for the project. OQ's for all observed employees are located in file for the project.</p>			
Corrective Action Required:		Follow-up Required:	
Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
		by (date): 10/11/19	
Inspector (Lead):		Date:	
Kyle Russo 			
Reviewer:		Date:	
		15 Oct 2019	