



Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	Perkins	Date(s):	11-14 May 2020
Company/Owner:	Intermountain Gas Company	Unit/OPID:	8160
Inspection Type & Time (1 day)	Total Inspection Days: 4		
Standard: <input type="checkbox"/>	Construction: <input checked="" type="checkbox"/> 4	Training: <input type="checkbox"/>	(T)(D) Integrity Management: <input type="checkbox"/> Incident: <input type="checkbox"/>
M/M: <input type="checkbox"/>	Follow-up: <input type="checkbox"/>	OQ: <input type="checkbox"/>	Damage Prevention: <input type="checkbox"/> D&A: <input type="checkbox"/>
Inspection Summary			
<p>A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company.</p> <p>11-14 May 2020: (3.5 Construction, .5 typed report) Observed a Dasco crew abandon service line 6842-371 and HPSS, replace with new service and tie into low pressure main at 617 Northside Blvd in Nampa. All procedures were followed. Typed up report</p> <p>Areas observed during this project were: Excavating, line locating, boring, welding, abandonment, bedding and backfilling, EFV installation, tie-in/hot tapping, service line install and pressure testing.</p> <p>Attachments: IPUC Form 4 Construction Inspections Das-co Daily Itineraries located in file for the project. OQ's for all observed employees are located in file for the project.</p>			
Corrective Action Required:		Follow-up Required:	
Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
		by (date):	
Inspector (Lead):		Date:	
Bruce Perkins 		5/14/2020	
Reviewer:		Date:	
Darrin Ulmer 		18 May 2020	