



Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	Perkins	Date(s):	14-Jul-20
Company/Owner:	Intermountain Gas Company	Unit/OPID:	8160
Inspection Type & Time (1 day)	Total Inspection Days: 1		
Standard: <input type="checkbox"/>	Construction: <input checked="" type="checkbox"/> 1	Training: <input type="checkbox"/>	(T)(D) Integrity Management: <input type="checkbox"/> Incident: <input type="checkbox"/>
M/M: <input type="checkbox"/>	Follow-up: <input type="checkbox"/>	OQ: <input type="checkbox"/>	Damage Prevention: <input type="checkbox"/> D&A: <input type="checkbox"/>
Inspection Summary			
A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company.			
<p>14 Jul 2020: (1.0 Construction)</p> <p>Observed a Das-co crew installing a new ¾" service line after tapping off a 2" steel line at 2700 S. Pond, Boise, Idaho. All procedures were followed. Typed up report</p> <p>Areas observed during this project were: Excavating, line locating, potholing, thumping, welding, plastic joining, backfilling, pressure testing and EFV test.</p> <p>Attachments: IPUC Form 4 Construction Inspections Das-co daily Itineraries located in file for the project. OQ's for all observed employees are located in file for the project.</p>			
Corrective Action Required:		Follow-up Required:	
Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
		by (date):	
Inspector (Lead):		Date:	
Bruce Perkins 		7/14/2020	
Reviewer:		Date:	
Darrin Ulmer 		16 Jul 2020	