

Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	Perkins	Date(s):	2-Jun-20
Company/Owner:	Intermountain Gas Company	Unit/OPID:	8160
Inspection Type & Time (1 day)	Total Inspection Days:		1
Standard: <input type="checkbox"/>	Construction: <input checked="" type="checkbox"/> 1	Training: <input type="checkbox"/>	(T)(D) Integrity Management: <input type="checkbox"/> Incident: <input type="checkbox"/>
M/M: <input type="checkbox"/>	Follow-up: <input type="checkbox"/>	OQ: <input type="checkbox"/>	Damage Prevention: <input type="checkbox"/> D&A: <input type="checkbox"/>
Inspection Summary			
A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company.			
<p>2 June 2020: (.8 Construction, .2 typed report) Observed a Das-co crew abandoning a 1/2" service and installing a new 3/4" service tee and service line at 2373 N Pleasant Hill Way in Boise, Idaho. All procedures were followed. Typed up report</p> <p>Attachments: IPUC Form 4 Construction Inspections Das-co daily Itineraries located in file for the project. OQ's for all observed employees are located in file for the project.</p>			
Corrective Action Required:	Follow-up Required:	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	by (date):	
Inspector (Lead):			Date:
Bruce Perkins			6/2/2020
Reviewer:			Date:
Darrin Ulmer			4 Jun 2020