



## Idaho PUC Pipeline Safety Inspection Summary

<b>Inspector(s):</b>	Perkins	<b>Date(s):</b>	27-May-20
<b>Company/Owner:</b>	Intermountain Gas Company	<b>Unit/OPID:</b>	8160
<b>Inspection Type &amp; Time (1 day)</b>	<b>Total Inspection Days:</b> 1		
Standard: <input type="checkbox"/>	Construction: <input checked="" type="checkbox"/> 1	Training: <input type="checkbox"/>	(T)(D) Integrity Management: <input type="checkbox"/> Incident: <input type="checkbox"/>
M/M: <input type="checkbox"/>	Follow-up: <input type="checkbox"/>	OQ: <input type="checkbox"/>	Damage Prevention: <input type="checkbox"/> D&A: <input type="checkbox"/>
<b>Inspection Summary</b>			
A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company.			
<p><b>27 May 2020:</b> (.5 Construction, .5 typed report)                  Observed a Dasco crew Installing new ¾" service lines to two different homes at 2593&amp;2647 E Bonita Hills Eagle, Idaho All procedures were followed. Typed up report</p> <p>Areas observed during this project were: Excavating, line locating, bedding ,backfilling, installing saddle tee, pressure testing and EFV installation/testing.</p> <p><b>Attachments:</b>                  IPUC Form 4 Construction Inspections                  Das-co Daily Itineraries located in file for the project.                  OQ's for all observed employees are located in file for the project.</p>			
<b>Corrective Action Required:</b>	<b>Follow-up Required:</b>	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		by (date):	
<b>Inspector (Lead):</b>		<b>Date:</b>	
Bruce Perkins		5/27/2020	
<b>Reviewer:</b>		<b>Date:</b>	
Darrin Ulmer		27 May 2020	