Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	Perkins/Brooks		Date(s):	28-29 Dec 2020
ompany/Owner: Intermountain Gas		Unit/OPID:	8160	
company, owner.		ountain das	omy or ib.	8100
Inspection Type & Time (1 day, 0.5 day)	Total Ir	spection Days:	4
Standard: Construction: M/M: Follow-up:		Γ)(D) Integrity Management: Damage Prevention:	Incident:	
Inspection Summary				
A construction inspection was performed on Das-Co, a contractor for Intermountain Gas Company				
28-29 December 2020 (4.0) construction) Observed a Das-co crew installing new 2" service line at 16570 Northside Blvd, Nampa, Idaho. All procedures were followed. Typed up report. Areas observed during this project were: traffic control, line locating, trenching, boring, pot-holing, installing riser, met-fit/continental fittings, blowing pigs, bedding/backfill, verified OQ's Attachments: IPUC Form 4 Construction Inspections Das-co daily iteneraries located in file for the project. OQ's for all observed employees are located in file for the project. Pictures of job ticket.				
Corrective Action Required:		Yes	No	Х
Follow-up Required:	by (date):	Yes	No	Х
Inspector (Lead):	S MAA	11	Date:	
Bruce Perkins	The felt		29-Dec-20 <i>2</i> 0	
Reviewer: ´ Darrin Ulmer	Jackth	HL	Date:	