



Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	Perkins	Date(s):	3-Jun-20
Company/Owner:	Intermountain Gas Company	Unit/OPID:	8160
Inspection Type & Time (1 day)	Total Inspection Days:		1
Standard: <input type="checkbox"/>	Construction: <input checked="" type="checkbox"/> 1	Training: <input type="checkbox"/>	(T)(D) Integrity Management: <input type="checkbox"/> Incident: <input type="checkbox"/>
M/M: <input type="checkbox"/>	Follow-up: <input type="checkbox"/>	OQ: <input type="checkbox"/>	Damage Prevention: <input type="checkbox"/> D&A: <input type="checkbox"/>
Inspection Summary			
A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company.			
<p>3 June 2020: (.8 Construction, .2 typed report)</p> <p>Observed a Das-co crew installing a new ¾" service line inside a 2" PE pipe being used as a sleeve because of rocky ground at 3800 Airport Rd in Nampa, Idaho. All procedures were followed. Typed up report</p> <p>Areas observed during this project were: Excavating, line locating, boring, bedding, EFV installation, service line install and pressure testing.</p> <p>Attachments: IPUC Form 4 Construction Inspections Das-co daily Itineraries located in file for the project. OQ's for all observed employees are located in file for the project.</p>			
Corrective Action Required:		Follow-up Required:	
Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
		by (date):	
Inspector (Lead):		Date:	
Bruce Perkins 		6/3/2020	
Reviewer:		Date:	
Darrin Ulmer 		4 Jun 2020	