



Mark Hunter

Engineer Interlocking Systems

Northwest

BNSF Railway Company

8310 Nieman Rd.

Lenexa, KS, 66219

913-577-8934

Mark.Hunter@BNSF.com

7/7/2017

BNR-R-17-01

BNSF Railway Clearance Waiver Request

For East Hauser Control Point

Track and Time Point Sign

Summary: BNSF Railway would like to request a clearance waiver for IDAPA 31.71.01 Rule 301 Side Clearance in General. We are installing a "Track and Time Point Sign" between mains 3 and 5 for the East Hauser control point. It is located at MP 45.79 on the BNSF Spokane Sub. Outside edge of the sign will be no less than 6'6" from the centerlines of mains 3 and 5. The sign will be less than 3' from the top of the rail. Attached is a drawing of the size of sign we will be using. This request is due to the need for a point of reference for authority to work on the track.

Mark Hunter

BNSF Railway

Engineer Interlocking Systems, Northwest

