

EXECUTIVE OFFICES

INTERMOUNTAIN GAS COMPANY

555 SOUTH COLE ROAD • P.O. BOX 7608 • BOISE, IDAHO 83707 • (208) 377-6000 • FAX: 377-6097

RECEIVED

2019 DEC 20 AM 9:57

IDAHO PUBLIC
UTILITIES COMMISSION

December 17, 2019

Mr. Darrin Ulmer
Pipeline Safety,
Program Manager
Idaho Public Utilities Commission
P.O. Box 83720-0074
Boise, ID 83720-0074

Subject: HPSS Serving Three or More Service Line Review

Dear Mr. Ulmer,

This letter is intended to address NOPVs I201902 and I201904 by providing the current scope of High Pressure Service Sets (HPSS) with three or more services downstream on Intermountain Gas Company's (IGC) system.

As of the March 2019 GIS data gathering, there were 83 HPSS with three or more services that were remaining on IGC's system. The following is an overview of the mitigation plan. Out of the 83 HPSS identified:

- 12 were found to have fewer than three services; these were either previously addressed by Field Operations or were included in the data due to an attribute error in GIS.
- 22 have either been removed or are going to be removed in 2019/2020.
- 27 have been reduced to fewer than three services downstream or are planned to be reduced in 2019/2020.
- 22 have been converted to regulator stations or are scheduled to be converted in 2019/2020.

Attached, you will find a detailed spreadsheet listing each remaining HPSS shown as having three or more services downstream, their locations, and respective mitigation plans.

Please contact me at (208) 377-6032 with questions or comments.

Respectfully Submitted,



Greg Watkins
Manager, Policy and Procedure
Intermountain Gas Company