Northwest Gas Processing (NWGP 117 E. Calhoun St. (box 500) Magnolia, AR 71753 870.234.3080

RECEIVED

2020 JUL 20 PH 12: 52

Attention Mr. Darrin Ulmer and Bruce Perkins Idaho Public Utilities Commission 11331 W. Chinden Blvd, Bldg 8, Suite 201-A Boise, ID 83714-1021

Subject: Response to Probable Violations

July 14, 2020

Hello Bruce and Darrin,

Enclosed/Attached please find response to your recently delivered Probable Violations. As we've discussed, due to the recent Bankruptcy filing of the previous operator of the subject line, we've had encountered issues in attempting to retrieve some of the requested data.

However, we have, and or are in the process of testing to ensure the subject issues have been addressed to ensure safety, and furthermore have every intention of maintaining compliance moving forward as the managing member of NWGP, it's facilities and gathering lines.

We appreciate your time working with us through this transition, and please do not hesitate to contact myself or Mr. Stephen Hernandez with The Compliance Group whom is helping us resolve and bring to date these issues.

Truly yours

Nate Caldwell

Mr. Darrin M. Ulmer Pipeline Safety, Program Manager Idaho Public Utility Commission

Subject:

Plan of Correction

Report # N202002

Dear Mr. Ulmer -

Northwest Gas Processing (NWGP) is submitting this letter to your office to update the Idaho Public Utility Commission's Pipeline Safety Division on NWGP's progress for resolution of the alleged violations from report number N202002.

Item No 1

Description:

§195.605(a) Procedural manual for operations, maintenance,

and emergencies.

Finding:

NWGP has no evidence of readings at test points or casings

occurred in 2019, other than rectifiers.

NWGP

Response:

NWGP cannot locate the cathodic protection test point readings in 2019. Test point readings were taken in March of 2020. There

were no indications of inadequate cathodic protection during this

inspection.

Item No 2

Description:

§195.743(a) Pressure limiting and regulating stations: Capacity

of relief devices.

Finding:

NWGP has no records that the testing of relief devices in place

or by review and calculations.

NWGP does not have any relief devices on this pipeline. The

pipeline is protected by pressure switches and shut down valves. Reviewing the capacity of the safety devices is not relevant for

Response:

NWGP

this system.

Item No 3

Description:

§195.615(b)(2) Emergency Plans

Finding:

NWGP has no records that this training has taken place

NWGP

NWGP will conduct an emergency training and table top or drill

Response:

in 2020.

Item No 4

Description: §195.709(c) Transmission Lines: Record Keeping

NWGP has no records / evidence of Cathodic Protection

Finding: readings at test points or casings occurred in 2019, other than

rectifiers.

NWGP cannot locate the cathodic protection test point readings

NWGP in 2019. Test point readings were taken in March of 2020. There

Response: were no indications of inadequate cathodic protection during this

inspection.

NWGP is committed to full compliance with the Administrations rules and appreciates your consideration in this matter.

Sincerely,

Nathan Caldwell Operations Manager Northwest Gas Processing