



Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	Russo	Date(s):	12-Sep-19
Company/Owner:	Intermountain Gas Company	Unit/OPID:	8160
Inspection Type & Time (1 day)	Total Inspection Days: 1		
Standard: <input type="checkbox"/>	Construction: <input checked="" type="checkbox"/> 1	Training: <input type="checkbox"/>	(T)(D) Integrity Management: <input type="checkbox"/> Incident: <input type="checkbox"/>
M/M: <input type="checkbox"/>	Follow-up: <input type="checkbox"/>	OQ: <input type="checkbox"/>	Damage Prevention: <input type="checkbox"/> D&A: <input type="checkbox"/>
Inspection Summary			
<p>A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company.</p> <p>12 Sept 2019: (1.0 Construction) Observed a Dasco crew excavating for a new service. They used proper installation methods and maintained separation from other utilities in trench. Typed up report.</p> <p>Areas observed during this project were: Excavating, Installation, Coupling, Backfilling, Purging</p> <p>Attachments: IPUC Form 4 Construction Inspections Das-co Daily Itineraries located in file for the project. OQ's for all observed employees are located in file for the project.</p>			
Corrective Action Required:	Follow-up Required:		
Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	by (date):	
Inspector (Lead):			Date: 10/1/19
Kyle Russo			
Reviewer:			Date: Sept 16, 2019