



Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	Perkins	Date(s):	16-Nov-20
Company/Owner:	Intermountain Gas	Unit/OPID:	8160
Inspection Type & Time (1 day, 0.5 day)	Total Inspection Days:		1
Standard: <input type="checkbox"/>	Construction: <input checked="" type="checkbox"/> 1	Training: <input type="checkbox"/>	(T)(D) Integrity Management: <input type="checkbox"/> Incident: <input type="checkbox"/>
M/M: <input type="checkbox"/>	Follow-up: <input type="checkbox"/>	OQ: <input type="checkbox"/>	Damage Prevention: <input type="checkbox"/> D&A: <input type="checkbox"/>
Inspection Summary			
<p>A construction inspection was performed on Das-Co, a contractor for Intermountain Gas Company</p> <p>16 November 2020 (1.0) construction)</p> <p>Observed a Das-co crew installing a new ¾" service lines and stubs at 2605/2624 E Ashlar Dr, Meridian, Idaho. All procedures were followed. Typed up report.</p> <p>Areas observed during this project were: Excavating, line locating, pressure testing, EFV install, bedding/backfilling, riser install and purging</p> <p>Attachments: IPUC Form 4 Construction Inspections Das-co daily itineraries located in file for the project. OQ's for all observed employees are located in file for the project. Pictures of job ticket.</p>			
Corrective Action Required:	Yes	No	X
Follow-up Required:	by (date):	Yes	No X
Inspector (Lead):			Date:
Bruce Perkins			16-Nov-2020
Reviewer:			Date:
Darrin Ulmer			17 Nov 2020