



Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	Perkins	Date(s):	27-Oct-20
Company/Owner:	Intermountain Gas Company	Unit/OPID:	8160
Inspection Type & Time (1 day)	Total Inspection Days:		1
Standard: <input type="checkbox"/>	Construction: <input checked="" type="checkbox"/> 1	Training: <input type="checkbox"/>	(T)(D) Integrity Management: <input type="checkbox"/> Incident: <input type="checkbox"/>
M/M: <input type="checkbox"/>	Follow-up: <input type="checkbox"/>	OQ: <input type="checkbox"/>	Damage Prevention: <input type="checkbox"/> D&A: <input type="checkbox"/>
Inspection Summary			
A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company.			
<p>27 Oct 2020: (1.0 Construction)</p> <p>Observed a Das-co crew installing a new 2" main using met fit couplings and ¾" service line at 1115 N Whitley Dr Nampa, Idaho. All procedures were followed. Typed up report</p> <p>Areas observed during this project were: Excavating, met fit couplings, line locating, pressure testing, EFV install, bedding/backfilling, riser install and purging</p> <p>Attachments:</p> <p>IPUC Form 4 Construction Inspections Das-co daily Itineraries located in file for the project. OQ's for all observed employees are located in file for the project. Pictures of Job ticket.</p>			
Corrective Action Required:		Follow-up Required:	
Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
		by (date):	
Inspector (Lead):		Date:	
Bruce Perkins 		10/27/2020	
Reviewer:		Date:	
Darrin Ulmer 		3 Nov 2020	