

# Idaho PUC Pipeline Safety Inspection Summary

<b>Inspector(s):</b>	Perkins	<b>Date(s):</b>	29-Oct-20
<b>Company/Owner:</b>	Intermountain Gas Company	<b>Unit/OPID:</b>	8160
<b>Inspection Type &amp; Time (1 day)</b>	<b>Total Inspection Days:</b> 1		
Standard: <input type="checkbox"/>	Construction: <input checked="" type="checkbox"/> 1	Training: <input type="checkbox"/>	(T)(D) Integrity Management: <input type="checkbox"/> Incident: <input type="checkbox"/>
M/M: <input type="checkbox"/>	Follow-up: <input type="checkbox"/>	OQ: <input type="checkbox"/>	Damage Prevention: <input type="checkbox"/> D&A: <input type="checkbox"/>
<b>Inspection Summary</b>			
A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company.			
<p><b>29 Oct 2020:</b> (1.0 Construction)                  Observed a Das-co crew tapping a 4" main and installing a new ¾" service line at 12172 W Savage Dr Boise, Idaho. All procedures were followed. Typed up report.</p> <p>Areas observed during this project were: Excavating, line locating, saddle/tapping T install, EFV install, riser install and purging.</p> <p><b>Attachments:</b>                  IPUC Form 4 Construction Inspections                  Das-co daily Itineraries located in file for the project.                  OQ's for all observed employees are located in file for the project.                  Pictures of Job ticket.</p>			
<b>Corrective Action Required:</b>		<b>Follow-up Required:</b>	
Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
		by (date):	
<b>Inspector (Lead):</b>		<b>Date:</b>	
Bruce Perkins		10/29/2020	
<b>Reviewer:</b>		<b>Date:</b>	
Darrin Ulmer		3 Nov 2020	