



# Idaho PUC Pipeline Safety Inspection Summary

<b>Inspector(s):</b>	Perkins	<b>Date(s):</b>	29-30 Sep 2020
<b>Company/Owner:</b>	Intermountain Gas Company	<b>Unit/OPID:</b>	8160
<b>Inspection Type &amp; Time (1 day)</b>	<b>Total Inspection Days:</b>		2
Standard: <input type="checkbox"/>	Construction: <input checked="" type="checkbox"/> 2	Training: <input type="checkbox"/>	(T)(D) Integrity Management: <input type="checkbox"/> Incident: <input type="checkbox"/>
M/M: <input type="checkbox"/>	Follow-up: <input type="checkbox"/>	OQ: <input type="checkbox"/>	Damage Prevention: <input type="checkbox"/> D&A: <input type="checkbox"/>
<b>Inspection Summary</b>			
<p>A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company and IGC personnel tapping crew.</p> <p><b>29-30 Sep 2020:</b> (2.0 Construction)                  Observed a Das-co crew extending a 4" steel main at 33400 Orchard Access, Boise, Idaho. IGC personnel tapped the main on 30 September 2020. All procedures were followed. Typed up report.</p> <p>Areas observed during this project were: Excavating, line locating, welding, EFV installation, material handling, backfilling/bedding, jeepping, coating repair and line tapping.</p> <p><b>Attachments:</b>                  IPUC Form 4 Construction Inspections                  Das-co daily Itineraries located in file for the project.                  OQ's for all observed employees are located in file for the project.</p>			
<b>Corrective Action Required:</b>		<b>Follow-up Required:</b>	
Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		Yes <input type="checkbox"/> No <input type="checkbox"/>	
<b>Inspector (Lead):</b>		<b>Date:</b>	
Bruce Perkins 		9/30/2020	
<b>Reviewer:</b>		<b>Date:</b>	
Darrin Ulmer 		1 Oct 2020	