


Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	Perkins	Date(s):	30-Jan-20
Company/Owner:	Intermountain Gas Company	Unit/OPID:	8160
Inspection Type & Time (1 day)	Total Inspection Days: 1		
Standard: <input type="checkbox"/>	Construction: <input checked="" type="checkbox"/> 1	Training: <input type="checkbox"/>	(T)(D) Integrity Management: <input type="checkbox"/> Incident: <input type="checkbox"/>
M/M: <input type="checkbox"/>	Follow-up: <input type="checkbox"/>	OQ: <input type="checkbox"/>	Damage Prevention: <input type="checkbox"/> D&A: <input type="checkbox"/>
Inspection Summary			
<p>A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company.</p> <p>30 Jan 2020: (1.0 Construction) Observed a Das-co crew locating/exposing a ¾" stub, installing meter bar, installed EFV and a tee for an additional home, pressure testing and backfilling. Typed up report</p>			
Attachments:			
IPUC Form 4 Construction Inspections Das-co Daily Itineraries located in file for the project. OQ's for all observed employees are located in file for the project.			
Corrective Action Required:		Follow-up Required:	
Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
		by (date):	
Inspector (Lead):		Date:	
Bruce Perkins		1/30/2020	
Reviewer:		Date:	
		31 Jan 2020	