


Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	Ulmer/Brooks	Date(s):	Aug-Dec 2020
Company/Owner:	Intermountain Gas Company	Unit/OPID:	8160
Inspection Type & Time (1 day)	Total Inspection Days:		26
Standard: <input type="checkbox"/>	Construction: <input checked="" type="checkbox"/> 26	Training: <input type="checkbox"/>	(T)(D) Integrity Management: <input type="checkbox"/> Incident: <input type="checkbox"/>
M/M: <input type="checkbox"/>	Follow-up: <input type="checkbox"/>	OQ: <input type="checkbox"/>	Damage Prevention: <input type="checkbox"/> D&A: <input type="checkbox"/>
Inspection Summary			
A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company.			
<p>24 Aug - Dec 2020: (1.0 Construction)</p> <p>Observed a Das-co crew installing new 6" Steel (over 17,000 ft) and 4" PE (over 22,000 ft) Mains from S. 10th Ave east along Orchard Ave to Middleton Rd and multiple cross streets in Caldwell, Idaho. All procedures were followed.</p> <p>Areas observed during this project were: Excavating, Pipe handling, welding, plastic joining, tracer wire installation, cad-welding, test post installation, reg station installation, bedding/backfilling.</p> <p>Attachments: IPUC Form 4 Construction Inspections Das-co daily Itineraries located in file for the project. OQ's for all observed employees are located in file for the project.</p> <p>Dates: Aug: 24, 25, 26, 27 Sept: 21, 22, 23, 28, 29, 30 Oct: 13, 14, 15, 26, 27, 28, 29 Nov: 16, 17, 18, 24, 25 Dec: 9, 10</p>			
Corrective Action Required:		Follow-up Required:	
Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
		by (date):	
Inspector (Lead):		Date:	
		5 Jan 21	
Reviewer:		Date:	